

Figure 1

100




Figure 2a





Figure 2b



Mobile terminals being compensated

120_{51}-M	120_{52}-M	120_{53}-M
120_{52}-M		
120_{53}-M	120_{53}-M	

Mobile terminals listed below the header are phantoms to the mobile terminals in the header.

Figure 3

Figure 10




Figure 5




Figure 6




Figure 7




Figure 8





Figure 9



Mobile terminals
being compensated

220 ₅₁ -DM	220 ₅₂ -DM	220 ₈₃ -DM	220 ₉₄ -DM	220 ₉₅ -DM	220 ₅₆ -DM
220 ₅₂ -DM					
220 ₈₃ -DM	220 ₈₃ -DM				
220 ₉₄ -DM	220 ₉₄ -DM	220 ₉₄ -DM			
220 ₉₅ -DM	220 ₉₅ -DM	220 ₉₅ -DM	220 ₉₅ -DM		
220 ₅₆ -DM					

Mobile terminals listed below the header are
phantoms to the mobile terminals in the header.

Figure 10

Figure 11

900

